



Need good Heatsink
TIC 253B

+ -15 Turns Shower resistance
2 Ohms

* = Adjust current to the batteries
** = Adjust to shutdown when batteries reach 28Vcc
*** Se necessario, Elevar o Valor. (Em Funcao dos picos)

www.esquemas.org
Green Led On = Full charge
Red led flashing = Charging